

Oil Field Environmental Incident Summary

Incident: 20160606101149 **Date/Time of Notice:** 06/06/2016 10:11

Responsible Party: ABRAXAS PETROLEUM CORP.

Well Operator: ABRAXAS PETROLEUM CORP.

Well Name: THOMPSON 44-16H

Field Name: AMBROSE

Well File #: 14888

Date Incident: 6/4/2016 **Time Incident:** 06:30

Facility ID Number:

County: DIVIDE

Twp: 163

Rng: 99

Sec: 16

Qtr:

Location Description:

Submitted By: SCARLET HOLGUIN

Received By:

Contact Person: KEVIN PORTRA
18803 MEISNER DRIVE
SAN ANTONIO, TX 78258

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/22/2016

Clean Up Concluded: 6/4/2016

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Fire department was called.

Wastes Disposal Location: none were recovered

Agencies Involved: Local Fire Department

Updates

Date: 6/6/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire occurred on the well pad. NDIC takes oversight.